



2102


RECEIVED DATA BLOCK: ERROR=0×0
VERIFYING RECEIVED DATA...


13t


FIG.3a


















































FIG. 11A




FIG.11B









FIG.11C











Adam E. Meggitt, et al. Filed: September 23, 2003 Our Docket No.: 283-392.11

For: Memory Data Copying System For Devices
Attorney of Record: George S. Blasiak
Telephone: (315) 425-9000 - 3K ้⊜ Fig. Me III 1728 Fig. 175 107 Fig. 179 <u>可</u>(の) W 1728 Fig 17h 10 (الانانانان Fig. 17: Fig. 17j

